

DECORATION SPEC SHEET

PORT **AUTHORITY**.

J852 Port Authority® Puffer Jacket





FRONT DECORATION DIMENSIONS					
COL	Collar Left	1"H X 4"W			
COR	Collar Right	1"H X 4"W			
LC	Left Chest	4" H X 4" W	Primary		
RC	Right Chest	4" H X 4" W			

BACK DECORATION DIMENSIONS					
ВА	Back	12" H X 12" W			
ВВ	Back Bottom	4" H X 12" W			
COBC	Collar Back	1"H X 4"W			
UB	Upper Back	4" H X 12" W			

SLEEVE DECORATION DIMENSIONS					
FSL	Full Sleeve Left	4" H X 14" W			
FSR	Full Sleeve Right	4" H X 14" W			
LS	Left Shoulder	4" H X 4" W			
LW	Left Wrist	4" H X 4" W			
RS	Right Shoulder	4" H X 4" W			
RW	Right Wrist	4" H X 4" W			

DECORATION SPEC SHEET

PORT AUTHORITY.

J852 Port Authority® Puffer Jacket

Decoration range is dependent on product, decoration method and equipment used. Allow for 1/8" per size. Sizing is based off: Adult–L, Women's–M, Youth–L, Girls–M. Please consult with your decorator or supplier.

DECORATION TECHNIQUES







EMBROIDERY

SCREEN PRINTING

HEAT TRANSFERS

ESSENTIAL PRODUCT INFORMATION

TIPS FROM OUR EXPERTS BY DECORATION TECHNIQUE



EMBROIDERY

Embroidery is the art of embellishing a piece of apparel with a needle and thread or yarn creating stunning visual representations of various types of art. This is achieved by converting logos in a digitizing software and using various stitch patterns, angles, density and stitch types to create depth, movement and detail. Thread can be made from many materials. The most commonly used threads are polyester and rayon. There are also options such as metallic, cotton, nylon, silk and even Nomex thread for fire resistance. Embroidery has a very high-perceived value and is popular for use on most apparel, bags, hats, luggage, blankets and more!

In order to maintain waterproof integrity, please consult with your decorator, equipment, and consumable supplier for best practices.

Water Proof/Coated Fabric with bonded barrier- 65/9 or 70/10 coated Sharp



SCREEN PRINTING

Point

An imprinting method in which the image is transferred to the fabric. Ink is squeegeed through a stenciled screen stretched over a frame and then cured in a dryer.

Low-cure poly inks are required. Grey or black bleed blockers may be necessary.

Avoid hot stacking when decorating 100% polyester, blends, and pigment dye fabrics.

DECORATION SPEC SHEET

PORT AUTHORITY.

J852 Port Authority® Puffer Jacket

Do not package product until completely cool. Cooling stations are recommended.

Bonding catalysts may be required for stain release, water resistant/waterproof coated and nylon fabrics.aggressive adhesive are required for stain release, water resistant/waterproof coated and nylon fabrics. Consult with your transfer supplier for recommendations.



HEAT TRANSFERS

A graphic, name and or number applied to a textile with a heat press. Great for quantities of any size, sports name and numbering, fashion, performance wear, print on demand programs and on-site decorating events.

Heat transfers with low cure adhesive and bleed blockers are required for this product.

Avoid hot stacking when decorating 100% polyester, blends, and pigment dye fabrics.